




584033

1419477

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

|   |        |  |  |                          |  |  |      |  |                   |                 |  |
|---|--------|--|--|--------------------------|--|--|------|--|-------------------|-----------------|--|
| <b>UNIFORM HAZARDOUS WASTE MANIFEST</b>   |        | 1. Generator ID Number<br><b>WAD980738546</b>  |  | 2. Page 1 of<br><b>1</b> |  | 3. Emergency Response Phone<br><b>(877) 577-2669</b> |      | 4. Manifest Tracking Number<br><b>000030716 DAT</b>  |                   |                 |  |
|   |        | 5. Generator's Name and Mailing Address<br><b>ALASKAN COPPER WORKS ATTN JERRY THOMPSON<br/>628 HANFORD ST<br/>SEATTLE WA 98134 (206)382-8379</b> |  |                          |  |  |      | Generator's Site Address (if different than mailing address)<br><b>ALASKAN COPPER WORKS<br/>628 S HANFORD<br/>SEATTLE WA 98134 (206)382-8379</b> |                   |                 |  |
| 6. Transporter 1 Company Name<br><b>Burlington Environmental, LLC</b>   |        | U.S. EPA ID Number<br><b>WAR000001743</b>  |  |                          |  |  |      | 7. Transporter 2 Company Name  |                   |                 |  |
| 8. Designated Facility Name and Site Address<br><b>BURLINGTON ENVIRONMENTAL, LLC. TACOMA PLANT<br/>1701 East Alexander Avenue<br/>Tacoma, WA 98421 (253) 627-7568</b>   |        | U.S. EPA ID Number<br><b>WAD020257945</b>  |  |                          |  |  |      |  |                   |                 |  |
| <b>GENERATOR</b>  | 9a. HM | 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))                                   |  |                          |  | 10. Containers                                       |      | 11. Total Quantity   | 12. Unit Wt./Vol. | 13. Waste Codes |  |
|   |        |  |  |                          |  | No.  | Type |  |                   |                 |  |
|   | X      | 1. <b>UN3266 WASTE CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S. (SODIUM HYDROXIDE) 8 PGI RQ(D002)</b>  |  |                          |  | 1  | TT   | 109  | G                 | D002            |  |
|   |        | 2.   |  |                          |  |  |      |  |                   |                 |  |
|   |        | 3.   |  |                          |  |  |      |  |                   |                 |  |
|   | 4.     |  |  |                          |  |  |      |  |                   |                 |  |
| 14. Special Handling Instructions and Additional Information<br><b>(1) 451878-01 - ER6(154) ALKALINE PARTS WASHI<br/>P.O.# 10708-MKB-69242/3200</b>   |        |  |  |                          |  |  |      |  |                   |                 |  |
| 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. |        |  |  |                          |  |  |      |  |                   |                 |  |
| Generator's/Offor's Printed/Typed Name<br><b>Genzo Thompson</b>   |        |  |  |                          |  |  |      |  |                   |                 |  |
| Signature<br>   |        |  |  |                          |  |  |      |  |                   |                 |  |
| Month Day Year<br><b>11/12/12</b>   |        |  |  |                          |  |  |      |  |                   |                 |  |
| 16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:  |        |  |  |                          |  |  |      |  |                   |                 |  |
| 17. Transporter Acknowledgment of Receipt of Materials  |        |  |  |                          |  |  |      |  |                   |                 |  |
| Transporter 1 Printed/Typed Name<br><b>RONALD J. DORRAN</b>   |        |  |  |                          |  |  |      |  |                   |                 |  |
| Signature<br>   |        |  |  |                          |  |  |      |  |                   |                 |  |
| Month Day Year<br><b>11/12/12</b>   |        |  |  |                          |  |  |      |  |                   |                 |  |
| Transporter 2 Printed/Typed Name  |        |  |  |                          |  |  |      |  |                   |                 |  |
| Signature   |        |  |  |                          |  |  |      |  |                   |                 |  |
| Month Day Year  |        |  |  |                          |  |  |      |  |                   |                 |  |
| 18. Discrepancy   |        |  |  |                          |  |  |      |  |                   |                 |  |
| 18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection   |        |  |  |                          |  |  |      |  |                   |                 |  |
| 18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number  |        |  |  |                          |  |  |      |  |                   |                 |  |
| Facility's Phone:   |        |  |  |                          |  |  |      |  |                   |                 |  |
| 18c. Signature of Alternate Facility (or Generator) Month Day Year  |        |  |  |                          |  |  |      |  |                   |                 |  |
| 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)   |        |  |  |                          |  |  |      |  |                   |                 |  |
| 1. <b>H141</b> 2. 3. 4.   |        |  |  |                          |  |  |      |  |                   |                 |  |
| 20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a  |        |  |  |                          |  |  |      |  |                   |                 |  |
| Printed/Typed Name<br><b>Wanda Grondahl</b>   |        |  |  |                          |  |  |      |  |                   |                 |  |
| Signature<br>   |        |  |  |                          |  |  |      |  |                   |                 |  |
| Month Day Year<br><b>11/12/12</b>   |        |  |  |                          |  |  |      |  |                   |                 |  |

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

AKC-0015988

Form Approved. OMB No. 2050-0039

DESIGNATED FACILITY TO GENERATOR

| UNIFORM HAZARDOUS WASTE MANIFEST  |  | 1. Generator ID Number | 2. Page 1 of   | 3. Emergency Response Phone | 4. Manifest Tracking Number |                    |                 |  |
|---|--|------------------------|--|-----------------------------|-----------------------------|--------------------|-----------------|--|
|   |  | MD0000730548           | 1  | (877) 577-2661              | 000030716 DAT               |                    |                 |  |
| 5. Generator's Name and Mailing Address   |  |                        | Generator's Site Address (if different than mailing address)             |                             |                             |                    |                 |  |
| GLASCO COPPER WORKS WITH JERRY THOMPSON<br>628 HUNTER ST<br>SEATTLE WA 98134 (206)382-8379  |  |                        | GLASCO COPPER WORKS<br>628 S HUNTER ST<br>SEATTLE WA 98134 (206)382-8379 |                             |                             |                    |                 |  |
| Generator's Phone:  |  |                        |  |                             |                             |                    |                 |  |
| 6. Transporter 1 Company Name   |  |                        | U.S. EPA ID Number   |                             |                             |                    |                 |  |
| 7. Transporter 2 Company Name   |  |                        | U.S. EPA ID Number   |                             |                             |                    |                 |  |
| 8. Designated Facility Name and Site Address  |  |                        | U.S. EPA ID Number   |                             |                             |                    |                 |  |
| SUN LING YIN ENVIRONMENTAL, LLC. TACOMA PLANT<br>1701 East Alexander Avenue<br>TACOMA WA 98401 (253) 671-7566   |  |                        | MD0010257945   |                             |                             |                    |                 |  |
| Facility's Phone:   |  |                        |  |                             |                             |                    |                 |  |
| 9a. HM  | 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any)) |                        | 10. Containers   |                             | 11. Total Quantity          | 12. Unit Wt./Vol.  | 13. Waste Codes |  |
|   |  |                        | No.  | Type                        |                             |                    |                 |  |
|   | 1. HAZARDOUS WASTE COMPOSITE LIQUID, BASIC, INORGANIC, A.O.S. (SODIUM HYDROXIDE) & 6011 (H20002)               |                        |  | 11                          | 109                         | P                  | 8002            |  |
|   | 2.   |                        |  |                             |                             |                    |                 |  |
|   | 3.   |                        |  |                             |                             |                    |                 |  |
|   | 4.   |                        |  |                             |                             |                    |                 |  |
| 14. Special Handling Instructions and Additional Information  |  |                        |  |                             |                             |                    |                 |  |
| (1) (1070-01) TWISTED IRON/IN THE PARTS WASH<br>PDA 10708-MKB-67247/2007  |  |                        |  |                             |                             |                    |                 |  |
| 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. |  |                        |  |                             |                             |                    |                 |  |
| Generator's/Offor's Printed/Typed Name  |  |                        | Signature  |                             |                             | Month Day Year     |                 |  |
| 16. International Shipments   |  |                        | Port of entry/exit:  |                             |                             | Date leaving U.S.: |                 |  |
| <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.   |  |                        |  |                             |                             |                    |                 |  |
| Transporter signature (for exports only):   |  |                        |  |                             |                             |                    |                 |  |
| 17. Transporter Acknowledgment of Receipt of Materials  |  |                        |  |                             |                             |                    |                 |  |
| Transporter 1 Printed/Typed Name  |  |                        | Signature  |                             |                             | Month Day Year     |                 |  |
| Transporter 2 Printed/Typed Name  |  |                        | Signature  |                             |                             | Month Day Year     |                 |  |
| 18. Discrepancy   |  |                        |  |                             |                             |                    |                 |  |
| 18a. Discrepancy Indication Space   |  |                        | Quantity   |                             |                             | Type               |                 |  |
|   |  |                        | Residue  |                             |                             | Partial Rejection  |                 |  |
|   |  |                        | Full Rejection   |                             |                             |                    |                 |  |
| 18b. Alternate Facility (or Generator)  |  |                        | Manifest Reference Number:   |                             |                             | U.S. EPA ID Number |                 |  |
| Facility's Phone:   |  |                        |  |                             |                             |                    |                 |  |
| 18c. Signature of Alternate Facility (or Generator)   |  |                        |  |                             |                             | Month Day Year     |                 |  |
| 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)   |  |                        |  |                             |                             |                    |                 |  |
| 1.  |  |                        | 2.   |                             |                             | 3.                 |                 |  |
| 4.  |  |                        |  |                             |                             |                    |                 |  |
| 20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a  |  |                        |  |                             |                             |                    |                 |  |
| Printed/Typed Name  |  |                        | Signature  |                             |                             | Month Day Year     |                 |  |

**U.S. EPA Form 8700-22**

Read all instructions before completing this form.

1. This form has been designed for use on a 12-pitch (elite) typewriter which is also compatible with standard computer printers; a firm point pen may also be used—press down hard.
2. Federal regulations require generators and transporters of hazardous waste and owners or operators of hazardous waste treatment, storage, and disposal facilities to complete this form (EPA Form 8700-22) and, if necessary, the continuation sheet (EPA Form 8700-22A) for both inter- and intrastate transportation of hazardous waste.

Public reporting burden for this collection of information is estimated to average: 30 minutes for generators, 10 minutes for transporters, and 25 minutes for owners or operators of treatment, storage, and disposal facilities. This includes time for reviewing instructions, gathering data, completing, reviewing and transmitting the form. Any correspondence regarding the PRA burden statement for the manifest must be sent to the Director of the Collection Strategies Division in EPA's Office of Information Collection at the following address: U.S. Environmental Protection Agency (2822T), 1200 Pennsylvania Ave., NW., Washington, DC 20460. Do not send the completed form to this address.

**I. Instructions for Generators**

**Item 1. Generator's U.S. EPA Identification Number**

Enter the generator's U.S. EPA twelve digit identification number, or the State generator identification number if the generator site does not have an EPA identification number.

**Item 2. Page 1 of \_\_\_\_\_**

Enter the total number of pages used to complete this Manifest (i.e., the first page (EPA Form 8700-22) plus the number of Continuation Sheets (EPA Form 8700-22A), if any).

**Item 3. Emergency Response Phone Number**

Enter a phone number for which emergency response information can be obtained in the event of an incident during transportation. The emergency response phone number must:

1. Be the number of the generator or the number of an agency or organization who is capable of and accepts responsibility for providing detailed information about the shipment;
2. Reach a phone that is monitored 24 hours a day at all times the waste is in transportation (including transportation related storage); and
3. Reach someone who is either knowledgeable of the hazardous waste being shipped and has comprehensive emergency response and spill cleanup/incident mitigation information for the material being shipped or has immediate access to a person who has that knowledge and information about the shipment.

**Note:** Emergency Response phone number information should only be entered in Item 3 when there is one phone number that applies to all the waste materials described in Item 9b. If a situation (e.g., consolidated shipments) arises where more than one Emergency Response phone number applies to the various wastes listed on the manifest, the phone numbers associated with each specific material should be entered after its description in Item 9b.

**Item 4. Manifest Tracking Number**

This unique tracking number must be pre-printed on the manifest by the forms printer.

**Item 5. Generator's Mailing Address, Phone Number and Site Address**

Enter the name of the generator, the mailing address to which the completed manifest signed by the designated facility should be mailed, and the generator's telephone number. Note, the telephone number (including area code) should be the normal business number for the generator, or the number where the generator or his authorized agent may be reached to provide instructions in the event the designated and/or alternate (if any) facility rejects some or all of the shipment. Also enter the physical site address from which the shipment originates only if this address is different than the mailing address.

**Item 6. Transporter 1 Company Name, and U.S. EPA ID Number**

Enter the company name and U.S. EPA ID number of the first transporter who will transport the waste. Vehicle or driver information may not be entered here.

**Item 7. Transporter 2 Company Name and U.S. EPA ID Number**

If applicable, enter the company name and U.S. EPA ID number of the second transporter who will transport the waste. Vehicle or driver information may not be entered here.

If more than two transporters are needed, use a Continuation Sheet(s) (EPA Form 8700-22A).

**Item 8. Designated Facility Name, Site Address, and U.S. EPA ID Number**

Enter the company name and site address of the facility designated to receive the waste listed on this manifest. Also enter the facility's phone number and the U.S. EPA twelve digit identification number of the facility.

**Item 9. U.S. DOT Description (Including Proper Shipping Name, Hazard Class or Division, Identification Number, and Packing Group)**

**Item 9a.** If the wastes identified in Item 9b consist of both hazardous and nonhazardous materials, then identify the hazardous materials by entering an "X" in this Item next to the corresponding hazardous material identified in Item 9b.

**Item 9b.** Enter the U.S. DOT Proper Shipping Name, Hazard Class or Division, Identification Number (UN/NA) and Packing Group for each waste as identified in 49 CFR 172. Include technical name(s) and reportable quantity references, if applicable.

**Note:** If additional space is needed for waste descriptions, enter these additional descriptions in Item 27 on the Continuation Sheet (EPA Form 8700-22A). Also, if more than one Emergency Response phone number applies to the various wastes described in either Item 9b or Item 27, enter applicable Emergency Response phone numbers immediately following the shipping descriptions for those items.

**Item 10. Containers (Number and Type)**

Enter the number of containers for each waste and the appropriate abbreviation from Table I (below) for the type of container.

**TABLE I.—TYPES OF CONTAINERS**

|   |                                   |
|---|-----------------------------------|
| BA = Burlap, cloth, paper, or plastic bags.             | DT = Dump truck.                  |
| CF = Fiber or plastic boxes, cartons, cases.            | DW = Wooden drums, barrels, kegs. |
| CM = Metal boxes, cartons, cases (including roll-offs). | HG = Hopper or gondola cars.      |
| CW = Wooden boxes, cartons, cases.                      | TC = Tank cars.                   |
| CY = Cylinders.   | TP = Portable tanks.              |
| DF = Fiberboard or plastic drums, barrels, kegs.        | TT = Cargo tanks (tank trucks).   |
| DM = Metal drums, barrels, kegs.                        |                                   |

**Item 11. Total Quantity**

Enter, in designated boxes, the total quantity of waste. Round partial units to the nearest whole unit, and *do not* enter decimals or fractions. To the extent practical, report quantities using appropriate units of measure that will allow you to report quantities with precision. Waste quantities entered should be based on actual measurements or reasonably accurate estimates of actual quantities shipped. Container capacities are not acceptable as estimates.

**Item 12. Units of Measure (Weight/Volume)**

Enter, in designated boxes, the appropriate abbreviation from Table II (below) for the unit of measure.

**TABLE II.—UNITS OF MEASURE**

|                                   |                         |
|-----------------------------------|-------------------------|
| G = Gallons (liquids only).       | N = Cubic Meters.       |
| K = Kilograms.                    | P = Pounds.             |
| L = Liters (liquids only).        | T = Tons (2000 Pounds). |
| M = Metric Tons (1000 kilograms). | Y = Cubic Yards.        |

**Note:** Tons, Metric Tons, Cubic Meters, and Cubic Yards should only be reported in connection with very large bulk shipments, such as rail cars, tank trucks, or barges.

**Item 13. Waste Codes**

Enter up to six federal and state waste codes to describe each waste stream identified in Item 9b. State waste codes that are not redundant with federal codes must be entered here, in addition to the federal waste codes which are most representative of the properties of the waste.

**Item 14. Special Handling Instructions and Additional Information**

1. Generators may enter any special handling or shipment-specific information necessary for the proper management or tracking of the materials under the generator's or other handler's business processes, such as waste profile numbers, container codes, bar codes, or response guide numbers. Generators also may use this space to enter additional descriptive information about their shipped materials, such as chemical names, constituent percentages, physical state, or specific gravity of wastes identified with volume units in Item 12.
2. This space may be used to record limited types of federally required information for which there is no specific space provided on the manifest, including any alternate facility designations; the manifest tracking number of the original manifest for rejected wastes and residues that are re-shipped under a second manifest; and the specification of PCB waste descriptions and PCB out-of-service dates required under 40 CFR 761.207. Generators, however, cannot be required to enter information in this space to meet state regulatory requirements.

**Item 15. Generator's/Officer's Certifications**

1. The generator must read, sign, and date the waste minimization certification statement. In signing the waste minimization certification statement, those generators who have not been exempted by statute or regulation from the duty to make a waste minimization certification under section 3002(b) of RCRA are also certifying that they have complied with the waste minimization requirements. The Generator's Certification also contains the required attestation that the shipment has been properly prepared and is in proper condition for transportation (the shipper's certification). The content of the shipper's certification statement is as follows: "I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent." When a party other than the generator prepares the shipment for transportation, this party may also sign the shipper's certification statement as the offeror of the shipment.
2. Generator or Offeror personnel may preprint the words, "On behalf of" in the signature block or may hand write this statement in the signature block prior to signing the generator/offeror certification, to indicate that the individual signs as the employee or agent of the named principal.

**Note:** All of the above information except the handwritten signature required in Item 15 may be pre-printed.





PNW - ESG - TRANSPORTATION GROUP

☐ RESOURCE RECOVERY 1629 East Alexander Ave., Tacoma WA 98421 (253) 383-3044  
☐ BEPUGET SOUND 1629 East Alexander Ave., Tacoma WA 98421 (253) 383-3044

# BILL OF LADING

|   |  |                            |         |                          |                        |                      |
|---|--|----------------------------|---------|--------------------------|------------------------|----------------------|
| DATE<br>1-12-12                               |  | BEGINNING MILEAGE<br>2502  |         | ON DUTY<br>0615          |                        | AM<br>PM             |
| DRIVER NAME<br>RONALD J. DOIRON               |  | ENDING MILEAGE             |         | OFF DUTY                 |                        | AM<br>PM             |
| VEHICLE NO.<br>2224                           |  | TRAILER NO.<br>6011        | BOX NO. | COST CENTER<br>8000      | SHIPPERS NO.<br>504033 | ORDER NO.<br>1419477 |
| SHIPPER / ORIGIN<br>NAME ALASKAN COPPER WORKS |  | WEIGH INFORMATION<br>GROSS |         | FOR OFFICE USE ONLY      |                        |                      |
| ADDRESS 628 S. HANFORD                        |  | TARE                       |         | MILEAGE                  |                        |                      |
| CITY SEATTLE STATE WA ZIP 98134               |  | NET                        |         | CONTAINER                |                        |                      |
| QUANTITY                                      |  | DOT PROPER SHIPPING NAME   |         | RATE                     |                        |                      |
| 1092 TT AS PER MANIFEST # 000030716 DAT       |  |                            |         | FREIGHT                  |                        |                      |
|   |  |                            |         | PLEASE PAY THIS AMOUNT → |                        |                      |

This is to certify that the above named materials are properly classified, described, packaged, marked and labeled, and are in proper condition for transportation, according to the applicable regulations of the Department of Transportation.

☒ DATE 1-12-12

## DESTINATION

|  |                                   |                                 |  |
|--|-----------------------------------|---------------------------------|--|
| NAME<br>BE, LLC                            |                                   | RECEIPT #                       |  |
| ADDRESS<br>1701 E. ALEXANDER AVE           |                                   |                                 |  |
| CITY<br>TACOMA                             | STATE<br>WA                       | ZIP<br>98421                    |  |
| VEHICLE NO.<br>2224                        | TRAILER NO.<br>6011               | DATE<br>1-12-12                 |  |
| <input checked="" type="checkbox"/> LOADED | <input type="checkbox"/> UNLOADED | <input type="checkbox"/> RINSED |  |

☒ TACOMA 1701 E. Alexander Ave., Tacoma, WA 98421 (253) 627-7568  
☐ WASHOUGAL 625 South 32nd St. (P.O. Box 229) Washougal, WA 98671 (360) 835-8594  
☐ KENT 20245 77th Ave. S., Kent, WA 98032 (253) 872-7859

|                    |                 |              |                 |
|--------------------|-----------------|--------------|-----------------|
| ARRIVAL TIME: 0730 |                 |              |                 |
| LOAD TIME:         |                 | UNLOAD TIME: |                 |
| START: 0730 AM     | HRS. FREE TIME  | START: AM    | HRS. FREE TIME  |
| FINISH: 0900 AM    | HRS. CHARGEABLE | FINISH: AM   | HRS. CHARGEABLE |

REASON FOR LOAD DELAY:

SIGNATURE FOR DELAY:

DRIVER SIGNATURE: Ronald J. Doiron

COMMENTS: MEASURED 54"

CUSTOMER COPY

AKC-0015992

**Burlington Environmental, LLC**

**RCRA Land Disposal Restriction Notification Form EZ**

*This form is applicable to characteristic wastes (D codes), listed wastes (F, K, U and P codes), California List Wastes, and Hazardous Debris.*

Generator: Alaskan Copper Works  
Profile #'s: 451878-01

U.S. EPA I.D. #: WAD980738546  
Manifest #: 0606307160AT

The wastes identified on this form are subject to the land disposal restrictions of 40 CFR Part 268. The wastes do not meet the treatment standards specified in Part 268, Subpart D or do not meet the applicable prohibition levels specified in 268.32. Pursuant to 40 CFR 268.7(a), the required information applicable to each waste is identified below (check all boxes that apply):

Treatability Group: ☐ Wastewater ☒ Nonwastewater  
(Wastewaters contain less than 1% filterable solids and less than 1% Total Organic Carbon)

- |   |  |
|---|--|
| <input type="checkbox"/> D001 Ignitable (except for High TOC) managed in non-CWA/non-CWA-equivalent/non Class I SDWA systems<br>(If this box is checked, complete Form UC to address underlying hazardous constituents) | <input type="checkbox"/> D001 Ignitable (except for High TOC) managed in CWA/ CWA-equivalent/Class I SDWA systems  |
| <input type="checkbox"/> D001 High TOC Ignitable (greater than 10% total organic carbon)  | <input checked="" type="checkbox"/> D002 Corrosive managed in non-CWA/non-CWA-equivalent/non Class I SDWA systems(Complete Form UC)                                |
| <input type="checkbox"/> D002 Corrosive managed in CWA/ CWA-equivalent/Class I SDWA systems   | <input type="checkbox"/> D003 Reactive Sulfides based on 261.23(a)(5)  |
| <input type="checkbox"/> D003 Reactive Cyanides based on 261.23(a)(5)   | <input type="checkbox"/> D003 Water Reactives based on 261.23(a)(2),(3) and (4) managed in a nonCWA/non-CWA equivalent/non Class I SDWA systems (Complete Form UC) |
| <input type="checkbox"/> D003 Water Reactives based on 261.23(a)(2),(3) and (4) managed in CWA/CWA-equivalent/ClassI SDWA systems   | <input type="checkbox"/> D003 Other Reactives based on 261.23(a)(1)  |
| <input type="checkbox"/> D004 Arsenic   | <input type="checkbox"/> D005 Barium   |
| <input type="checkbox"/> D007 Chromium  | <input type="checkbox"/> D008 Lead   |
| <input type="checkbox"/> D009 High mercury inorganic (>260 mg/kg total), including incinerator residue and residues from RMERC  | <input type="checkbox"/> D006 Cadmium  |
| <input type="checkbox"/> D009 High-mercury organic (>260 mg/kg total), not including incinerator residue  | <input type="checkbox"/> D006 Cadmium-containing batteries   |
| <input type="checkbox"/> D009 Low-mercury (<260 mg/kg total)  | <input type="checkbox"/> D008 Lead acid batteries  |
| <input type="checkbox"/> D010 Selenium  | <input type="checkbox"/> D009 All D009 wastewaters   |
| <input type="checkbox"/> D012 Endrin  | <input type="checkbox"/> D011 Silver   |
| <input type="checkbox"/> D013 Lindane   | <input type="checkbox"/> D023 o-Cresol   |
| <input type="checkbox"/> D014 Methoxychlor  | <input type="checkbox"/> D024 m-Cresol   |
| <input type="checkbox"/> D015 Toxaphene   | <input type="checkbox"/> D025 p-Cresol   |
| <input type="checkbox"/> D016 2,4-D   | <input type="checkbox"/> D026 Cresols (Total)  |
| <input type="checkbox"/> D017 2,4,5-TP (Silvex)   | <input type="checkbox"/> D027 p-Dichlorobenzene  |
| <input type="checkbox"/> D018 Benzene   | <input type="checkbox"/> D028 1,2-Dichloroethane   |
| <input type="checkbox"/> D019 Carbon tetrachloride  | <input type="checkbox"/> D029 1,1-Dichloroethylene   |
| <input type="checkbox"/> D020 Chlordane   | <input type="checkbox"/> D030 2,4-Dinitrotoluene   |
| <input type="checkbox"/> D021 Chlorobenzene   | <input type="checkbox"/> D031 Heptachlor   |
| <input type="checkbox"/> D022 Chloroform  | <input type="checkbox"/> D032 Hexachlorobenzene  |
|   | <input type="checkbox"/> D033 Hexachlorobutadiene  |
|   | <input type="checkbox"/> D034 Hexachloroethane   |
|   | <input type="checkbox"/> D035 Methyl ethyl ketone  |
|   | <input type="checkbox"/> D036 Nitrobenzene   |
|   | <input type="checkbox"/> D037 Pentachlorophenol  |
|   | <input type="checkbox"/> D038 Pyridine   |
|   | <input type="checkbox"/> D039 Tetrachloroethylene  |
|   | <input type="checkbox"/> D040 Trichloroethylene  |
|   | <input type="checkbox"/> D041 2,4,5-Trichlorophenol  |
|   | <input type="checkbox"/> D042 2,4,6-Trichlorophenol  |
|   | <input type="checkbox"/> D043 Vinyl chloride   |

**Note:** If any bolded entries are checked, form UC must be completed to address underlying hazardous constituents, unless the material is treated in a Clean Water Act (CWA) treatment process or unless otherwise noted above.

**In addition, the following wastes are included in this shipment:**

- ☐ F001-F005 spent solvents. (If this box is checked, complete the F001-F005 section on the back of this form. Check the hazardous waste number(s) that applies, and identify the constituents likely to be present in the waste.)
- ☐ F039 multisource leachate. (If this box is checked, complete and attach Form UC to identify the individual constituents.)
- ☐ Hazardous Debris (If this box is checked, complete the Hazardous Debris section on the back page of this form.)

If this shipment carries additional waste codes that are not addressed above, identify them here:

| EPA Waste Code | Subcategory (if applicable) | EPA Waste Code | Subcategory (if applicable) |
|----------------|-----------------------------|----------------|-----------------------------|
| _____          | _____                       | _____          | _____                       |
| _____          | _____                       | _____          | _____                       |
| _____          | _____                       | _____          | _____                       |

Check the box(es) that applies; identify the individual constituents likely to be present.

| <u>Hazardous waste description</u> |  | <u>Regulated hazardous constituents</u>   |  |
|------------------------------------|--|---|--|
| <input type="checkbox"/>           | F001 Spent halogenated solvents used in degreasing | Carbon tetrachloride<br>Tetrachloroethylene<br>Trichloroethylene<br>Trichloromonofluoromethane                  | Methylene chloride<br>1,1,1-Trichloroethane<br>1,1,2-Trichloro-1,2,2-trifluoroethane                               |
| <input type="checkbox"/>           | F002 Spent halogenated solvents                    | Chlorobenzene<br>Methylene chloride<br>1,1,1-Trichloroethane<br>Trichloroethylene<br>Trichloromonofluoromethane | <i>o</i> -Dichlorobenzene<br>Tetrachloroethylene<br>1,1,2-Trichloroethane<br>1,1,2-Trichloro-1,2,2-trifluoroethane |
| <input type="checkbox"/>           | F003 Spent non-halogenated solvents                | Acetone<br>Cyclohexanone<br>Ethyl benzene<br>Methanol<br>Xylenes (total)  | <i>n</i> -Butyl alcohol<br>Ethyl acetate<br>Ethyl ether<br>Methyl isobutyl ketone                                  |
| <input type="checkbox"/>           | F004 Spent non-halogenated solvents                | <i>m</i> -Cresol<br><i>p</i> -Cresol<br>Nitrobenzene  | <i>o</i> -Cresol<br>Cresol-mixed isomers (cresylic acid)   |
| <input type="checkbox"/>           | F005 Spent non-halogenated solvents                | Benzene<br>2-Ethoxyethanol<br>Methyl ethyl ketone<br>Pyridine   | Carbon disulfide<br>Isobutyl alcohol<br>2-Nitropropane<br>Toluene  |

\*The treatment standards for carbon disulfide, cyclohexanone, and methanol nonwastewaters are based on the TCLP and apply to spent solvent nonwastewaters containing only one, two, or all three of these constituents. The treatment standards for these three constituents do not apply when any of the other F001-F005 constituents are present in the waste.

#### Hazardous Debris

- ☐ This shipment contains hazardous debris that will be treated to comply with the alternative treatment standards of 268.45 (e.g., macroencapsulation or abrasive blasting).

*(The definitions of "debris" and "hazardous debris" are in 40 CFR 268.2. Per 268.45, hazardous debris must be treated for each "contaminant subject to treatment." To determine these, look up the waste code in 268.40 and list the regulated hazardous constituents for each code.)*

The contaminants subject to treatment for this debris are identified below:

| <u>EPA Waste Code</u> | <u>Subcategory</u> | <u>Contaminants subject to treatment</u> |       |
|-----------------------|--------------------|--|-------|
| _____                 | _____              | _____                                    | _____ |
| _____                 | _____              | _____                                    | _____ |
| _____                 | _____              | _____                                    | _____ |
| _____                 | _____              | _____                                    | _____ |
| _____                 | _____              | _____                                    | _____ |

**Burlington Environmental, LLC**  
**RCRA Land Disposal Restriction Notification Form UC**

Generator: Alaskan Copper Works  
Profile #: 451878-01

U.S. EPA I.D. #: WA1980738546  
Manifest #: 000030716 D4T

*In accordance with 40 CFR 268.7(a), the underlying hazardous constituents must be addressed in this waste. Per 268.2(i), "underlying hazardous constituent" means any constituent listed in 268.48, Table UTS—Universal Treatment Standard which can reasonably be expected to be present at the point of generation of the hazardous waste, at a concentration above the constituent-specific UTS treatment standard. Refer to Form-EZ (attached) for the waste code(s), treatability group, and subcategory applicable to this waste.*

*In order to address underlying hazardous constituents in characteristic wastes, please check the appropriate box:*

- ☒ I have reviewed the UTS list of 268.48, and per 268.7(a), I have determined that there are no underlying hazardous constituents reasonably expected to be present in this waste.
- ☐ I have reviewed the UTS list of 268.48, and per 268.7(a), I have determined that underlying hazardous constituents are present in this waste. The underlying hazardous constituents are identified as follows:

|       |       |       |
|-------|-------|-------|
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |
| _____ | _____ | _____ |

*The determination of underlying hazardous constituents was based on:*


- ☒ Generator's knowledge of the waste
- ☐ Analysis

I certify that I personally have examined and am familiar with the waste through analysis and testing, or through knowledge of the waste to support this certification. I certify that as an authorized representative of the generator named above, all the information submitted in this notification is true and correct to the best of my knowledge.

\_\_\_\_\_  
Printed Name

\_\_\_\_\_  
Signature

\_\_\_\_\_  
Date



**SIGN  
HERE**







P.O.# 10708-MKB-69242/3200

Los Angeles  
800-800-0039  
626-333-7678  
Fax # 626-333-4065

Portland  
800-676-7678  
503-684-9335  
Fax # 503-684-0332

San Jose  
800-800-2478  
408-571-2231  
Fax # 408-571-2279

Phoenix  
800-395-7378  
480-813-6118  
Fax# 480-813-6183

Seattle  
800-488-7678  
206-575-4994  
Fax # 206-575-6920

Denver  
888-371-7678  
303-371-5000  
Fax # 303-371-2993

Dallas  
800-834-9391  
817-834-7678  
Fax # 817-834-7680

San Diego  
858-552-0801  
Fax # 858-552-0988

[www.PortPlastics.com](http://www.PortPlastics.com)